# Unpaid Related Instruction Requirements Roofing

The apprentice must complete satisfactorily <u>40 hours</u> of unpaid school hours, as prescribed by the ABC of WI Apprenticeship Advisory Committee.

### **Mandatory**

#### First Aid/CPR/OSHA

The apprentice shall obtain certification in First Aid and CPR and a minimum of a Construction 10-Hour OSHA Safety course during the first 12 months of the contract. The First Aid and CPR certifications must be kept current.

Please do NOT take online First Aid, CPR, OSHA 10, or OSHA 30 courses, as they are not approved by the committee.

Who to contact to register for First Aid and CPR:

- ABC of WI Apprenticeship and Training Trust (800-829-9926 or www.abcwi.org and look under "Upcoming Events")
- American Heart Association at (www.americanheart.org)
- American Red Cross (www.redcross.org)
- Hospital
- Fire department
- Technical College

Who to contact to register for OSHA:

- ABC of WI Apprenticeship and Training Trust (800-829-9926 or www.abcwi.org and look under "Upcoming Events")
- Technical College

#### • Transition to Trainer

The apprentice is required to take the 8-hour Transition to Trainer course in the final year of the apprenticeship.

## Other:

- Rigging and Lifting
- Qualified Signaler/Rigger
- Safety classes/conference
- Blueprint reading